A. SOLENOID WAS WIRED OPEN.

25X1A

T 81527)

- B. GROUND CHECK HAS NOT BEEN MADE AS SUGGESTED HOWEVER MAINS ARE FEEDING PROPERLY INDICATING PRESSURE, SHUTOFF VALVE TO SLIPPER HAS BEEN AND FOUND TO OPERATE. SLIPPERS HAD SOME PRESSURE WHEN CAPS OPENED AFTER LANDING. SUGGESTED CHECK WILL BE MADE.
- C. ONLY CHANGE IS REMOVAL OF AIR SCOOPS FROM AUX TANKS WHICH WAS ACCOMPLISHED AFTER FERRY FLIGHT.
- D. NEGATIVE ELECTRICAL WORK. COUNTER APPEARED TO OPERATE NORMALLY SECOND FLIGHT.
- E. MAINTENANCE SUGGESTS POSSIBILITY OF MALFUNCTION AUX SNIFFLE VALVE.

END OF MESSAGE

fm/

25X1A